



C368 Software Release Notes

V1.48

The C368 software update V1.48, is a maintenance release that includes the following changes:

- Improved BluOS Auto Sense. When a track is selected in the BluOS App, the C368 powers ON at source BluOS.
Note: Network Standby and Auto Sense need to be set to "On" in the Settings menu.
- Speaker, Subwoofer, Pre-Out and Local Headphones are muted in Bluetooth (Source) mode.

New Features

- Support for future MDC modules.

Upgrade Procedure

- Follow the [TD2016-03-C368_C388 Software Upgrade Procedure](#)